

## Hermetic Booster **Spares List**



**Contact Eclipse for Ordering Information**

Part Number	Description
10010600	0.5 HP Motor for HB-3314/ HB-3412/ HB-4412 (208/1/60/3600/ 56 Frame)
10002176	0.5 HP Motor for HB-3314/ HB-3412/ HB-4412 (208/3/60/3600/ 56 Frame)
20993	0.5 HP Motor for HB-3412/ HB-4412/ HB-3314 (115/230/1/60/3600/ 56 Frame)
20994	0.5 HP Motor for HB-3412/ HB-4412/ HB-3314/ HB-3315 (208-230/460/3/60/3600/ 56 Frame)
20997	0.75 HP Motor for HB-3316 (115/230/1/60/3600/ 56 Frame)
20997-1	0.75 HP Motor for HB-3316 (208/1/60/3600/ 56 Frame)
10002177	0.75 HP Motor for HB-3316 (208/3/60/3600/ 56 Frame)
20996	0.75 HP Motor for HB-3316 (208-230/460/3/60/3450/ 56 Frame)
10002178	1.0 HP Motor for HB-4412/ HB-4414/ HB-4614/ HB-4615/ HB-4617 (208/3/60/3600/ 56 Frame)
20995	1.0 HP Motor for HB-4412/ HB-4414/ HB-4614/ HB-4615/ HB-4617 (208-230/460/3/60/3600/ 56 Frame)
10054758	1.5 HP Motor for HB-4614/ HB-4617/ HB-4619/ HB-6615 (208/3/60/3600/ 143T Frame)
10056099	1.5 HP Motor for HB-4614/ HB-6615/ HB-4617/ HB-4619 (208-230/460/3/60/3600/ 143T Frame)
10054762	10.0 HP Motor for HB-4628/ HB-6623/ HB-8819/ HB-8828 (208/3/60/3600/ 213T Frame)
10054752	10.0 HP Motor for HB-8819/ HB-6623/ HB-4628/ HB-8828 (230/460/3/60/3600/ 215T Frame)
10054750	15.0 HP Motor for HB-8823/ HB-8828 (208/3/60/3600/ 254T Frame)
10054753	15.0 HP Motor for HB-8823/ HB-8828 (208-230/460/3/60/3600/ 254T Frame)
10054759	2.0 HP Motor for HB-4619/ HB-6615/ HB-6617 (208/3/60/3600/ 145T Frame)
10054746	2.0 HP Motor for HB-6615/ HB-6617/ HB-4619 (208-230/460/3/60/3600/ 145T Frame)
10054836	20.0 HP Motor for HB-8823/ HB-8828 (208/3/60/3600/ 256T Frame)
10054958	20.0 HP Motor for HB-8823/ HB-8828 (208-230/460/3/60/3600/ 256T Frame)
10002182	3.0 HP Motor for HB-4623/ HB-6617/ HB-6619 (208/3/60/3600/ 182T Frame)
10055852	3.0 HP Motor for HB-6617/ HB-6619/ HB-4623 (208-230/460/3/60/3600/ 182T Frame)
10054751	5.0 HP Motor for HB-8817/ HB-6619/ HB-4623/ HB-4628 (208/3/60/3600/ 184T Frame)
10054832	5.0 HP Motor for HB-8817/ HB-6619/ HB-4623/ HB-4628 (230/460/3/60/3600/ 184T Frame)
10054839	7.5 HP Motor for HB-4628/ HB-6623/ HB-8819 (208/3/60/3600/ 213T Frame)
10054749	7.5 HP Motor for HB-8819/ HB-6623/ HB-4628 (208-230/460/3/60/3500/ 213T Frame)
14093	Gasket for HB-3312, HB-3412, HB-4412, HB-4414
14549	Gasket for HB-3316

14019	Gasket for HB-4614, HB-4615
13823	Gasket for HB-4617, HB-6617-2
14222	Gasket for HB-4619, HB-6619-3
16558	Gasket for HB-4623, HB-8817
13734	Gasket for HB-4628, HB-8828
16800	Gasket for HB-6615
14793	Gasket for HB-6617-3
17959	Gasket for HB-6619-5
14377	Gasket for HB-6623, HB-8823
15353	Gasket for HB-8819
38005	Gasket Raw Material